

APPENDIX D

Site Photographs – Excavation



1. 7/20/06 – NWC boring NWC-X-39, prior to excavation, looking northwest.



3. Northwest corner of NWC excavation, looking northwest, showing deeper excavation to 5 feet.



2. 7/20/06 – Excavation of upper 2 feet, looking northeast. Note barrier wall on right.



4. Excavation, looking northeast from southwest corner. Note areas of deeper excavation to 5 feet. Note barrier wall on east side of excavation.



5. 7/21/06 – Excavation looking southeast from northwest corner. Note barrier wall on east side of excavation.



6. 7/21/06 – Excavation complete to 5 feet, looking northeast. Concrete pile in left foreground.



7. 7/21/06 – Stockpiled soil from NWC excavation (to be disposed of off site).



8. 7/21/06 – NWC after excavation and backfill.



9. 7/21/06 – Backfill and compaction of northwest corner using vibratory roller.